

HUSQVARNA MOTORCYCLES RECALLS MY22 FE AND TE MODELS

ALL ENDURO MACHINES TO BE INSPECTED BY AN AUTHORISED HUSQVARNA MOTORCYCLES DEALER DUE TO REPLACEMENT OF LOCKING SPLIT PINS

Valid for all markets

Husqvarna Motorcycles is recalling all MY22 FE and TE models due to the availability of improved locking split pins for the brake pad holding brackets in the front and rear brake calipers.

The issue may not be apparent on all motorcycles, however, owners of these models are required to return their machine to an authorised Husqvarna Motorcycles dealer who will ensure to replace the previous pins with the improved version on the front and rear brake calipers.

Customers who have already acquired one of the above-mentioned motorcycles are being informed by a personal letter and are asked to immediately contact an authorised Husqvarna Motorcycles Dealer to arrange an inspection appointment.

In addition, customers can check online in the '[Service](#)' area of the Husqvarna Motorcycles website to determine if their motorcycle is affected by this recall. The check and replacement of all parts involved will be carried out at no cost to the customer and must be performed by authorised Husqvarna Motorcycles Dealers only.

Further info on all authorised dealers can be found on Husqvarna Motorcycles' website:

<https://www.husqvarna-motorcycles.com/en-int/dealer-search.html>