

MEDIA INFORMATION, 12. 11. 2014

## RECALL OF HUSQVARNA OFFROAD MODELS TO AUTHORIZED DEALERS

**IN ORDER TO REVIEW THE CORRECT  
ASSEMBLING OF THE FRONT FORK,  
HUSQVARNA RECALLS FC AND FE  
AS WELL AS TE AND TC MODELS OF  
THE MODEL YEAR 2015 EQUIPPED  
WITH WP 4CS FORK TO AUTHORIZED  
HUSQVARNA DEALERS**

The recall is necessary in order to check the correct assembling of the fork's piston rod and screw cap and ensure maximum operational safety, function and quality of the front wheel.

Husqvarna does not have any information on accidents resulting from the manufacturing defect described above.

Customers of affected and already distributed motorcycles have been contacted in writing by Husqvarna. Furthermore, customers can also check online to find out if their motorcycle is affected. The recall information is available in the "**Servicecheck**" area of <http://www.husqvarna-motorcycles.com> and can be seen by entering the complete vehicle identification number (17 digit) and the ID number of the motorcycle's delivery certificate.

The professional check of the front fork can be carried out by authorized Husqvarna dealers only. This check is a guarantee that is completely free of charge and lasts at most 30 minutes.



**Husqvarna Motocross Model Range  
2015**



**Husqvarna Enduro Model Range  
2015**

**The recall action affects the following models:**

FC 250  
FC 350  
FC 450

FE 250  
FE 350  
FE 350S  
FE 450  
FE 501  
FE 501S

TC 125  
TC 250  
TE 125  
TE 250  
TE 300

**FOR FURTHER INFORMATION, PLEASE CONTACT:**

**Paolo Carrubba**  
Media and PR Manager  
Mobile +39 / 347 971 87 69  
Mail: [paolo.carrubba@husqvarna-motorcycles.com](mailto:paolo.carrubba@husqvarna-motorcycles.com)