

PRESS INFORMATION, 26.10.2015

## RECALL OF HUSQVARNA OFFROAD MODELS

Husqvarna Motorcycles recalls FE and FC bikes of model year 2016 in order to be checked at authorized Husqvarna Motorcycles Dealers.

During routine testing Husqvarna Motorcycles discovered that deviations in the manufacturing process of the supplier of the aluminium fuel pump nut can result in insufficient sealing and cause uncontrolled fuel leakage on FE 250, 350, 450 and FC 250 bikes of model year 2016.

All owners of affected and already delivered vehicles will be informed in writing by Husqvarna Motorcycles. More information or the information whether the respective motorcycle is affected by the recall can be gathered at the [Husqvarna Motorcycles Dealers](#).

The above-mentioned reviews can only be implemented by an authorized and qualified Husqvarna Motorcycles Dealer. This guaranteeing is free of charge.

[www.husqvarna-motorcycles.com](http://www.husqvarna-motorcycles.com)

[www.images.husqvarna-motorcycles.com](http://www.images.husqvarna-motorcycles.com)



*Husqvarna FE 250*



*Husqvarna FE 450*



*Husqvarna FC 250*

FOR FURTHER INFORMATION, PLEASE CONTACT:

**Paolo Carrubba**

Head of Media and Public Relations

M + 39 / 347 / 97 18 769

E [paolo.carrubba@husqvarna-motorcycles.com](mailto:paolo.carrubba@husqvarna-motorcycles.com)