

PRESS INFORMATION, 16.03.2017

RECALL OF SPECIFIC HUSQVARNA TC 50 MODELS

Husqvarna Motorcycles are recalling specific numbers of TC 50 minicycles of model year 2017 to authorised dealers in order to replace the chain connecting link.

Internal quality checks have established that a defective chain connecting link was installed in a small production lot of Husqvarna TC 50 models due to deviations in manufacturing at a supplier. This can lead to premature failure of the chain connecting link and possible consequential damage. Therefore, the link must be replaced on all affected motorcycles.

Customers to whom the affected motorcycles have already been delivered are being informed by a personal letter and are asked to immediately contact an authorised Husqvarna Motorcycles dealer to arrange an appointment for a replacement. In addition, customers can check online in the '[Service](#)' area of the [Husqvarna Motorcycles website](#) to determine if their motorcycle is affected by this recall.

The check and replacement of the chain connecting link will be carried out at no cost to the customer and must be performed by authorized Husqvarna dealers only.



**FOR FURTHER INFORMATION, PLEASE
CONTACT:**

Paolo Carrubba

Head of Media and Public Relations

M + 39 / 347 / 97 18 769

E paolo.carrubba@husqvarna-motorcycles.com