

## **HUSQVARNA MOTORCYCLES RECALL SPECIFIC NUMBERS OF TC 50 MODEL**

### **MODEL YEAR 2019 TC 50 MINICYCLES TO BE CHECKED AT AUTHORIZED HUSQVARNA MOTORCYCLES DEALERS**

VALID FOR ALL MARKETS

Husqvarna Motorcycles are recalling specific numbers of TC 50 of model year 2019 for an inspection of their carburettor.

During the carburettor assembly process for MY19 TC 50 models, the carburettor covers may have been fitted incorrectly. Considering the carburettor cover also acts as the upper throttle slide stop, this may lead to the throttle slide not operating smoothly.

To ensure that all TC 50 riders can continue enjoying maximum safety in all conditions, Husqvarna Motorcycles consider it important that the correct fitting of the carburettor cover is checked.

Customers who have already acquired one of the above mentioned motorcycles are being informed by a personal letter and are asked to immediately contact an authorised Husqvarna Motorcycles Dealer to arrange an inspection appointment.

In addition, customers can check online in the '[Service](#)' area of the [Husqvarna Motorcycles website](#) to determine if their motorcycle is affected by this recall. The check and replacement of all parts involved will be carried out at no cost to the customer and must be performed by authorized Husqvarna Motorcycles Dealers only.

Further info on all authorized dealers can be found on Husqvarna Motorcycles' website: [www.husqvarna-motorcycles.com/dealer-search](http://www.husqvarna-motorcycles.com/dealer-search)



TC 50 MY19