

HUSQVARNA MOTORCYCLES RECALLS MY 21 EE 5 MODEL

ALL-ELECTRIC MODEL TO BE CHECKED AT AUTHORISED HUSQVARNA MOTORCYCLES DEALERS

Valid for all markets

Husqvarna Motorcycles is recalling all model year 2021 EE 5 models in order for authorised Husqvarna Motorcycles dealers to check the battery vent valve due to possible nonconformities in the production process.

While the deviation may not be present on all motorcycles, to avoid unsafe battery conditions, Husqvarna Motorcycles is checking vent valve installation on all model year 2021 EE 5 models.

Customers who have already acquired one of the above-mentioned motorcycles are being informed by a personal letter and are asked to immediately contact an authorised Husqvarna Motorcycles Dealer to arrange an inspection appointment.

In addition, customers can check online in the '[Service](#)' area of the Husqvarna Motorcycles website to determine if their motorcycle is affected by this recall. The check and replacement of all parts involved will be carried out at no cost to the customer and must be performed by authorised Husqvarna Motorcycles Dealers only.

Further info on all authorised dealers can be found on Husqvarna Motorcycles' website: <https://www.husqvarna-motorcycles.com/en-int/dealer-search.html>